

# **Material Safety Data Sheet**

Material Name: HELIUM MSDS ID: Hynote-0039

## Section 1 - Product and Company Identification

Synonyms: Helium

Chemical Name: Helium

Formula: He

TDG (Canada) CLASSIFICATION: 2.2

WHMIS CLASSIFICATION: A

#### ShangHai Hynote

906#, Tower A, Tomson Center, 228 Zhang Yang Road, PuDong, Shang Hai, PRC.

**Product Information**: +86-379-65867058 **MSDS Information Email**: hynote@shtel.net.cn

## Section 2 - Composition/information on ingredients

**COMPOSITION**: 100% PEL-OSHA¹: Simple Asphyxiant **CAS NUMBER**: 7440-59-7 TLV-ACGIH₂: Simple Asphyxiant

**RTECS#**: MH6520000 LD<sub>50</sub> or LC<sub>50</sub> Route/Species: Not Available

Formula: He

#### Section 3 - Hazards Identification

#### **EMERGENCY OVERVIEW**

Simple Asphyxiant - This product does not contain oxygen and may cause asphyxia if released in a confined area. Maintain oxygen levels above 19.5%. Contact with product may cause frostbite or freeze burns in exposed tissues. Nonflammable.

## **EMERGENCY Telephone Numbers**:

+86-21-58790001 (In South China):

+86-379-65867058 (In North China)

+86-10-110/119/120 (24 Hours)

<sup>&</sup>lt;sup>1</sup> As stated in 29 CFR 1910, Subpart Z (revised July 1, 1993).

<sup>&</sup>lt;sup>2</sup> As stated in the ACGIH 1994-95 Threshold Limit Values for Chemical Substances and Physical Agents.

#### **ROUTE OF ENTRY:**

Skin Contact	Skin Absorption	Eye Contact	Inhalation	Ingestion
Yes	No	Yes	Yes	No

#### **HEALTH EFFECTS:**

Exposure Limits	Irritant	Sensitization		
No	No	No		
Teratogen	Reproductive Hazard	Mutagen		
No	No	No		
Synergistic Effects				
None Reported				

Carcinogenicity:

NTP:No IARC: No OSHA: No

#### **EYE EFFECTS**:

Contact with evaporating liquid may cause tissue freezing.

## **SKIN EFFECTS**:

Contact with rapidly evaporating liquid can cause cryogenic "burns" or frostbite. Frostbite effects are a change in color of the skin to gray or white, possibly followed by blistering.

#### **INGESTION EFFECTS:**

Ingestion is unlikely. Contact with product may cause tissue freezing.

#### **INHALATION EFFECTS:**

MEDA HAZADD CODEC

Product is a non-toxic simple asphyxiant. Effects of oxygen deficiency resulting from simple asphyxiants may include: rapid breathing, diminished mental alertness, impaired muscular coordination, faulty judgement, depression of all sensations, emotional instability, and fatigue. As asphyxiation progresses, nausea, vomiting, prostration, and loss of consciousness may result, eventually leading to convulsions, coma, and death.

Oxygen deficiency during pregnancy has produced developmental abnormalities in humans and experimental animals.

NFPA HAZARD CODES	HMIS HAZARD CODES	RATINGS SYSTEM
Health: 3	Health: 3	0 = No Hazard
Flammability: 0	Flammability: 0	1 = Slight Hazard
Reactivity: 0	Reactivity: 0	2 = Moderate Hazard
		3 = Serious Hazard
		4 = Severe Hazard

DATINGS SYSTEM

## Section 4- First Aid Measures

#### **EYES**

Never introduce ointment or oil into the eyes without medical advice! In case of freezing or cryogenic "burns" caused by rapidly evaporating liquid, DO NOT WASH THE EYES WITH HOT OR EVEN TEPID WATER! Remove victim from the source of contamination. Open eyelids



wide to allow liquid to evaporate. If pain is present, refer the victim to an ophthalmologist for treatment and follow up. If the victim cannot tolerate light, protect the eyes with a light bandage.

#### SKIN:

For dermal contact or frostbite: Remove contaminated clothing and flush affected areas with lukewarm water. DO NOT USE HOT WATER. A physician should see the patient promptly if contact with the product has resulted in blistering of the dermal surface or in deep tissue freezing.

#### **INGESTION**:

A physician should see the patient promptly if contact with the product has resulted in blistering of the dermal surface or in deep tissue freezing.

#### INHALATION:

PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE. RESCUE PERSONNEL SHOULD BE EQUIPPED WITH SELF-CONTAINED BREATHING APPARATUS. Victims should be assisted to an uncontaminated area and inhale fresh air. Quick removal from the contaminated area is most important. Unconscious persons should be moved to an uncontaminated area, and if breathing has stopped, administer artificial resuscitation and supplemental oxygen. Further treatment should be symptomatic and supportive.

## Section 5- Fire-Fighting Measures

Conditions of Flammability: Nonflammable			
Flash point: None Method: Not Ap		plicable	Autoignition Temperature: None
LEL(%): None		UEL(%):None	
Hazardous combustion products: None			
Sensitivity to mechanical shock: None			
Sensitivity to static discharge: None			

#### FIRE AND EXPLOSION HAZARDS:

None. Nonflammable.

#### **EXTINGUISHING MEDIA:**

None required. Use as appropriate for surrounding materials.

## Section 6- Accidental Release Measures

Evacuate all personnel from affected area. Use appropriate protective equipment. If leak is in user's equipment, be certain to purge piping with inert gas prior to attempting repairs. If leak is in container or container valve, contact the appropriate emergency telephone number listed in Section 1 or call your closest Hynote location.

## Section 7- Handling and Storage

Use only in well-ventilated areas in accordance with manufacturer's and Hynote instructions. These cylinders must ALWAYS be kept upright. Specialized trucks are needed for their movement. Do not drag, slide or roll cylinders. Stationary customer site vessels should be operated in accordance with the manufacturer's and Hynote's instructions. Do not attempt to repair, adjust or in any other way modify the operation of these vessels. If there is a malfunction or other type of operations problem with the vessel, contact the closest Hynote location immediately



for assistance.

Liquid helium is delivered into stationary vacuum jacketed vessels at the customer's location or in portable vacuum-jacketed "liquid" cylinders requiring special handling methods. Consult manufacturer's instructions.

Due to the extremely cold liquid, uninsulated transfer lines may condense air. The liquefied air may flash of nitrogen, leaving an oxygen enriched liquid. Do not allow the liquefied air to contact oils, greases, or other combustible materials such as asphalt and motor oil.

Vessels for liquid helium are designed specifically for helium service. Vessels and associated structures are not designed to support higher density fluids. Density, liquid at saturation pressure at 2.17 °K (-271 °C): 0.146 Kg/l.

For additional recommendations, consult Compressed Gas Association Pamphlets P-9, P-9.1, P-12, P-14 and Safety Bulletin SB-2.

Never carry a compressed gas cylinder or a container of a gas in cryogenic liquid form in an enclosed space such as a car trunk, van or station wagon. A leak can result in a fire, explosion, asphyxiation or a toxic exposure.

## Section 8- Exposure Controls/Personal Protection

#### **EXPOSURE LIMITS<sup>1</sup>:**

INGREDIENT	%VOLUME	PEL-OSHA <sup>2</sup>	TLV-ACGIH <sup>3</sup>	LD <sub>50</sub> or LC <sub>50</sub>
				Route/Species
Helium	100.0	Simple	Simple	Not Available
Formula: He		Asphyxiant	Asphyxiant	
CAS: 7440-59-7				
RTECS#: MH6520000				

<sup>&</sup>lt;sup>1</sup> Refer to individual state of provincial regulations, as applicable, for limits which may be more stringent than those listed here.

#### **ENGINEERING CONTROLS:**

Local exhaust to prevent accumulation of high concentrations so as to reduce the oxygen level in the air to less than 19.5%.

#### **EYE/FACE PROTECTION:**

Safety goggles or glasses as appropriate for the job. Faceshield recommended when handling cryogenic liquid material.

#### **SKIN PROTECTION:**

Protective gloves of material appropriate for the job. Insulated gloves recommended when handling cryogenic liquid material.

#### RESPIRATORY PROTECTION:

<sup>&</sup>lt;sup>2</sup> As stated in 29 CFR 1910, Subpart Z (revised July 1, 1993)

<sup>&</sup>lt;sup>3</sup> As stated in the ACGIH 1994-1995 Threshold Limit Values for Chemical Substances and Physical Agents.



Positive pressure air line with full-face mask and escape bottle or self-contained breathing apparatus should be available for emergency use.

## **OTHER/GENERAL PROTECTION:**

Safety shoes or other footwear as appropriate for the job.

## Section 9- Physical and Chemical Properties

PARAMETER	VALUE	UNITS	
Physical state (gas, liquid, solid)	: Gas		
Vapor pressure	: Above Critical temp		
Vapor density at STP ( $Air = 1$ )	: 0.14 (GAS)		
Evaporation point	: Not Available		
Boiling point	: -452.1	٥F	
	: -268.9	$^{\mathrm{o}}\mathrm{C}$	
Freezing point	: Not Available		
	: Not Available		
pH	: Not Applicable		
Specific gravity	: Not Available		
Oil/water partition coefficient	: Not Available		
Solubility (H <sub>2</sub> 0)	: Negligible		
Odor threshold	: Not Applicable		
Odor and appearance	: Colorless, odorless g	as	

## Section 10- Stability and Reactivity

## **STABILITY:**

Stable.

## **INCOMPATIBLE MATERIALS**

None.

#### **HAZARDOUS POLYMERIZATION:**

Does not occur.

## Section 11- Toxicological Information

Oxygen deficiency during pregnancy has produced developmental abnormalities in humans and experimental animals.

No data given in the Registry of Toxic Effects of Chemical Substances (RTECS) or Sax, Dangerous Properties of Industrial Materials, 7th ed.

## **Section 12- Ecological Information**

No data given.



## Section 13- Disposal Considerations

Do not attempt to dispose of residual waste or unused quantities. Return in the shipping container PROPERLY LABELED, WITH ANY VALVE OUTLET PLUGS OR CAPS SECURED AND VALVE PROTECTION CAP IN PLACE to HYNOTE Gases or authorized distributor for proper disposal.

#### **Section 14- Transport Information**

**DOT/IMO SHIPPING NAME**: Helium

**HAZARD CLASS**: 2.2

**IDENTIFICATION NUMBER: UN 1046** 

**PRODUCT RQ**: None

**SHIPPING LABEL(s)**: NONFLAMMABLE GAS

**PLACARD (when required)**: NONFLAMMABLE GAS

## Section 15- Regulatory Information

**SARA TITLE III - HAZARD CLASSES:** 

Sudden Release of Pressure Hazard

## Section 16- Other Information

Compressed gas cylinders shall not be refilled without the express written permission of the owner. Shipment of a compressed gas cylinder which has not been filled by the owner or with his/her (written) consent is a violation of transportation regulations.

## **DISCLAIMER OF EXPRESSED AND IMPLIED WARRANTIES:**

Although reasonable care has been taken in the preparation of this document, we extend no warranties and make no representations as to the accuracy or completeness of the information contained herein, and assume no responsibility regarding the suitability of this information for the user's intended purposes or for the consequences of its use. Each individual should make a determination as to the suitability of the information for their particular purpose(s).

#### **NOTICE TO READER:**

ALTHOUGH THE INFORMATION CONTAINED IN THIS DOCUMENT IS PRESENTED IN GOOD FAITH, BASED ON AVAILABLE INFORMATION BELIEVED TO BE RELIABLE AT THE TIME OF PREPARATION OF THIS DOCUMENT, SHANGHAI HYNOTE MAKES NO WARRANTIES OR REPRESENTATIONS WITH RESPECT TO THE INFORMATION OR THE PRODUCT/MATERIALS DESCRIBED HEREIN, AND EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES AND CONDITIONS (INCLUDING ALL WARRANTIES AND CONDITIONS OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE). NO FREEDOM FROM INFRINGEMENT OF ANY PATENT OWNED BY SHANGHAI HYNOTE OR OTHERS IS TO BE INFERRED.

# HYNOTE GAS

THIS INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. PLEASE CONTACT SHANGHAI HYNOTE FOR THE MOST CURRENT VERSION OF THIS MSDS. SHANGHAI HYNOTE DOES NOT ASSUME RESPONSIBILITY FOR MSDS OBTAINED FROM THIRD PARTY SOURCES.UNLESS SPECIFICALLY AGREED OTHERWISE, SHANGHAI HYNOTE DOES NOT TAKE RESPONSIBILITY FOR USE, TRANSPORTATION, STORAGE, HANDLING OR DISPOSAL, OF THE PRODUCTS DESCRIBED HEREIN.